

Louisville Metro Air Pollution Control District

Excess Emission Event Reports

January 1, 2015 to January 31, 2015

Plant 36: CLARIANT CORPORATION WEST PLAN, 1227 S 12TH ST (Hansen Project #O-0036)

Review No: 1922305 **Started:** 1/6/2015 at 9:00 am **Stopped:** 1/6/2015 at 9:20 am **Logged:** 1/29/2015 at 12:00 am

Problem Description: **Pollutant:** NITROGEN OXIDES
Building 20 Scrubber emitting visible NOx for 15 minutes. pH adjustment wrong.

Reported: 1/6/2015 at 9:30 am **Status:** Open

1 Problem(s) Reported by CLARIANT CORPORATION WEST PLAN

Plant 72: FORD MOTOR COMPANY, 2000 FERN VALLEY RD (Hansen Project #O-0072)

Review No: 1922044 **Started:** 1/10/2015 at 11:39 am **Stopped:** 1/11/2015 at 11:00 am **Logged:** 1/20/2015 at 9:04 am

Problem Description: **Pollutant:** VOLATILE ORGANIC COMPOUNDS
On 1/10/2015, Denver Tomblin notified the District by both email and voicemail of an upset condition beginning at 11:39am involving the Eisenmann incinerator, which was caused by stoppage of the carbon wheel.

Reported: 11/10/2015 at 12:57 pm **Status:** DONE

Review No: 1922164 **Started:** 1/26/2015 at 6:35 am **Stopped:** 1/26/2015 at 7:23 am **Logged:** 1/26/2015 at 8:18 am

Problem Description: **Pollutant:** VOLATILE ORGANIC COMPOUNDS
On 1/26/2015, Erik Kaiser of Ford LAP notified APCD of an excess emissions event beginning at 6:35am and involving the Eisenmann incinerator.

Reported: 1/26/2015 at 8:08 am **Status:** Open

2 Problem(s) Reported by FORD MOTOR COMPANY

Plant 187: ECKART AMERICA L.P., 4101 CAMP GROUND RD (Hansen Project #O-0187)

Review No: 1921885 **Started:** 1/7/2015 at 10:21 am **Stopped:** 1/7/2015 at 10:22 am **Logged:** 1/7/2015 at 11:43 am

Problem Description: **Pollutant:** PARTICULATE MATTER PM
Ruprure of compression coupling in piping between Airslide (U-3: E-141/E-229) and Classifier 2 (U-6: E-128) released 500 lbs of aluminum powder for a period of 36 seconds.

Reported: 1/7/2015 at 11:43 am **Status:** INCIDENT

1 Problem(s) Reported by ECKART AMERICA L.P.
